

## SUMMARY

No. 2230820/6

Only valid in combination with the ISP GmbH test report no. 2230820/6, dated 16.10.2020.

Type of Testing: Performance Testing of a ceiling inspection clap in accordance with

DIN 18032-3, the German standard for sport halls, part 3: Halls for gymnastics, games and multi-purpose-use, testing of safety against

ball throwing (2018)

Applicant: Cewood SIA

Galdusalas 1

04336 Jaunlaicene

Latvia

Test Institute: ISP GmbH

Institut für Sportstättenprüfung

Amelunxenstraße 65 48167 Münster Germany

Product Name: Cewood System Ball Impact Inspection Clap

**Description:** Ceiling inspection clap with the dimensions (length x width) of approx.

400 mm x 400 mm that has been installed into the "Cewood System Ball

Impact" system, consisting of WW ceiling panels.

Test Results: The inspection clap "Cewood System Ball Impact Inspection Clap"

withstood the testing of safety against ball throwing with marginal visual changes. Therefore, the system is classed as safe against ball throwing for ceiling elements in accordance with 18032 part 3 (November 2018)

(ballwurfsicher für Deckenelemente).

Reproduction and publication of this document in shortened text and the use of advertising is permitted only with the written approval of the ISP GmbH.

The test results relate only to the tested samples.

Münster, 16.10.2020

Dennis Frank
MANAGING DIRECTOR

Germany